

Indiana Department of Environmental Management

We make Indiana a cleaner, healthier place to live.

Joseph E. Kernan Governor

Lori F. Kaplan Commissioner 100 North Senate Avenue P.O. Box 6015 Indianapolis, Indiana 46206-6015 (317) 232-8603 (800) 451-6027 www.in.gov/idem

February 11, 2004

Mr. Sean McGowan Franklin Power Products, Inc. d/b/a Western Reman Industrial A division of Franklin Power 1175 North Hoosier Boulevard Peru, Indiana 46970

> Re: 103-18655-00034 First Notice-only change to MSOP 103-15670-00034

Dear Mr. McGowan:

Power Investments, Inc. was issued a permit on September 6, 2002 for a stationary locomotive connecting rods and blowers manufacturing source. A letter notifying the Office of Air Quality of a change of legal name was received on January 29, 2004. Pursuant to the provisions of 326 IAC 2-6.1-6(d)(2) the permit is hereby revised as follows:

Power Investments, Inc. located at 1175 North Hoosier Boulevard, Peru, Indiana, name has been changed to the current legal name of Franklin Power Products, Inc., d/b/a Western Reman Industrial, a division of Franklin Power located at the same address. The appropriate reporting forms were updated to reflect the name change. The new Authorized Individuals will be remain as Sean McGowan, Plant Manager. These changes became effective January 21, 2004. All operations and methods of reporting remain unchanged.

All other conditions of the permit shall remain unchanged and in effect. Please attach a copy of this letter and the following revised permit pages to the front of the original permit.

This decision is subject to the Indiana Administrative Orders and Procedures Act - IC 4-21.5-3-5. If you have any questions on this matter, please contact Gary Freeman, at (800) 451-6027, ask for Gary Freeman or extension 3-5334, or dial (317) 233-5334.

Sincerely,

Original Signed by Paul Dubenetzky

Paul Dubenetzky, Chief Permits Branch Office of Air Quality

Attachments: Updated pages

PD/gkf

cc:

File - Miami County Miami County Health Department Air Compliance Section Inspector: Dave Rice

Compliance Data Section
Permit Review Section 1- Gary Freeman
Air Programs - Chet Bohannon

An Equal Opportunity Employer Recycled Paper

Please Recycle 🐧





MINOR SOURCE OPERATING PERMIT OFFICE OF AIR QUALITY

Franklin Power Products, Inc. d/b/a Western Reman Industrial a division of Franklin Power 1175 North Hoosier Boulevard Peru, Indiana 46970

(herein known as the Permittee) is hereby authorized to operate subject to the conditions contained herein, the emission units described in Section A (Source Summary) of this permit.

This permit is issued to the above mentioned company under the provisions of 326 IAC 2-1.1, 326 IAC 2-6.1 and 40 CFR 52.780, with conditions listed on the attached pages.

Operation Permit No.: MSOP 103-15670-00034	
Issued by: Paul Dubenetzky, Branch Chief Office of Air Quality	Issuance Date: September 6, 2002 Expiration Date: September 6, 2007

First Notice-Only Change: 103-18655-00034	Pages Affected: 23, 24 and 25	
Issued by: Original Signed by Paul Dubenetzky Paul Dubenetzky, Branch Chief Office of Air Quality	Issuance Date: February 11, 2004	

Franklin Power Products, Inc., d/b/a Western Reman Industrial, a division of Franklin Power
Page 23 of 25 Peru, Indiana First Notice-Only Change 103-18655

MSOP 103-15670-00034

Permit Reviewer: Aida De Guzman Changed by: Gary Freeman

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT OFFICE OF AIR QUALITY COMPLIANCE BRANCH

MINOR SOURCE OPERATING PERMIT ANNUAL NOTIFICATION

This form should be used to comply with the notification requirements under 326 IAC 2-6.1-5(a)(5).

Company Name:	Franklin Power Products, Inc., d/b/a Western Reman Industrial a division of Franklin Power
Address:	1175 North Hoosier Blvd.
City:	Peru
Phone #:	(765) 689-7620
MSOP #:	103-15670-00034

I hereby certify that Franklin Power Products, Inc., d/b/a Wester Reman Industrial, a division of Franklin Power is:

9 still in operation.

9 no longer in operation.

I hereby certify that Franklin Power Products, Inc., d/b/a Wester Reman Industrial, a division of Franklin Power is : 9 in compliance with the requirements of

MSOP **103-15670-00034**.

9 not in compliance with the requirements of MSOP **103-15670-00034**..

Authorized Individual (typed):	
Title:	
Signature:	
Date:	

If there are any conditions or requirements for which the source is not in compliance, provide a narrative description of how the source did or will achieve compliance and the date compliance was, or will be achieved.

Noncompliance:		

Page 24 of 25 Peru, Indiana MSOP 103-15670-00034 Permit Reviewer: Aida De Guzman	First Notice-Only Change 103-18655 Changed by: Gary Freeman	

Franklin Power Products, Inc., d/b/a Western Reman Industrial, a division of Franklin Power

MALFUNCTION REPORT INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT OFFICE OF AIR QUALITY FAX NUMBER - 317 233-5967

DATE/TIME CONTROL EQUIPMENT BACK-IN SERVICE//19AM/PM TYPE OF POLLUTANTS EMITTED: TSP, PM-10, SO2, VOC, OTHER: ESTIMATED AMOUNT OF POLLUTANT EMITTED DURING MALFUNCTION: MEASURES TAKEN TO MINIMIZE EMISSIONS: REASONS WHY FACILITY CANNOT BE SHUTDOWN DURING REPAIRS: CONTINUED OPERATION REQUIRED TO PROVIDE ESSENTIAL* SERVICES:	FAX NUMBER - 317 233-3907
THIS FACILITY MEETS THE APPLICABILITY REQUIREMENTS BECAUSE IT HAS POTENTIAL TO EMIT 25 TONS/YEAR PARTICULATE MATTER?, 25 TONS/YEAR SULFUR DIOXIDE?, 25 TONS/YEAR NITROGEN OXIDES?, 25 TONS/YEAR AND CONS/YEAR ENDOS AND SULFUR COMPOUNDS MEAD COMPOUNDS MEAD AND AND AND AND AND AND AND AND AND A	
THIS INCIDENT MEETS THE DEFINITION OF "MALFUNCTION" AS LISTED ON REVERSE SIDE? Y N THIS MALFUNCTION IS OR WILL BE LONGER THAN THE ONE (1) HOUR REPORTING REQUIREMENT? Y N COMPANY_Franklin Power Products, Inc. d/b/a Western Reman Industrial a division of Franklin Power HONE NO. (765) 689-7620 LOCATION: (CITY AND CO) 1175 North Hoosier Blvd., Peru, Indiana PERMIT NO. MSOP103-15670 AFS PLANT ID: 103-00034 AFS POINT ID: INSP: CONTROL/PROCESS DEVICE WHICH MALFUNCTIONED AND REASON: DATE/TIME MALFUNCTION STARTED: ///19 AM/PM ESTIMATED HOURS OF OPERATION WITH MALFUNCTION CONDITION: DATE/TIME CONTROL EQUIPMENT BACK-IN SERVICE ///19 AM/PM TYPE OF POLLUTANTS EMITTED: TSP, PM-10, SO2, VOC, OTHER: ESTIMATED AMOUNT OF POLLUTANT EMITTED DURING MALFUNCTION: MEASURES TAKEN TO MINIMIZE EMISSIONS: REASONS WHY FACILITY CANNOT BE SHUTDOWN DURING REPAIRS: CONTINUED OPERATION REQUIRED TO PROVIDE ESSENTIAL* SERVICES:	THIS FACILITY MEETS THE APPLICABILITY REQUIREMENTS BECAUSE IT HAS POTENTIAL TO EMIT 25 TONS/YEAR PARTICULATE MATTER?, 25 TONS/YEAR SULFUR DIOXIDE?, 25 TONS/YEAR NITROGEN OXIDES?, 25 TONS/YEAR VOC?, 25 TONS/YEAR HYDROGEN SULFIDE?, 25 TONS/YEAR TOTAL REDUCED SULFUR ?, 25 TONS/YEAR REDUCED SULFUR COMPOUNDS?, 25 TONS/YEAR FLUORIDES?, 100TONS/YEAR CARBON MONOXIDE?, 10 TONS/YEAR ANY SINGLE HAZARDOUS AIR POLLUTANT?, 25 TONS/YEAR ANY COMBINATION HAZARDOUS AIR POLLUTANT?, 1 TON/YEAR LEAD OR LEAD COMPOUNDS MEASURED AS ELEMENTAL LEAD?, OR IS A SOURCE LISTED UNDER 326 IAC 2-5.1-3(2)? EMISSIONS FROM MALFUNCTIONING CONTROL EQUIPMENT OR PROCESS EQUIPMENT CAUSED EMISSIONS IN EXCESS OF APPLICABLE LIMITATION THIS MALFUNCTION RESULTED IN A VIOLATION OF: 326 IAC, OR, PERMIT CONDITION # AND/OR PERMIT
COMPANY: Franklin Power Products, Inc. d/b/a Western Reman Industrial a division of Franklin Power HONE NO. (765) 689-7620 LOCATION: (CITY AND CO) 1175 North Hoosier Blvd., Peru, Indiana PERMIT NO. MSOP103-15670 AFS PLANT ID: 103-00034 AFS POINT ID:	THIS INCIDENT MEETS THE DEFINITION OF 'MALFUNCTION' AS LISTED ON REVERSE SIDE ? Y N
LOCATION: (CITY AND CO) 1175 North Hoosier Blvd., Peru, Indiana PERMIT NO. MSOP103-15670 AFS PLANT ID: 103-00034 AFS POINT ID: INSP: CONTROL/PROCESS DEVICE WHICH MALFUNCTIONED AND REASON: DATE/TIME MALFUNCTION STARTED: // 19 AM/PM ESTIMATED HOURS OF OPERATION WITH MALFUNCTION CONDITION: DATE/TIME CONTROL EQUIPMENT BACK-IN SERVICE // 19 AM/PM TYPE OF POLLUTANTS EMITTED: TSP, PM-10, SO2, VOC, OTHER: ESTIMATED AMOUNT OF POLLUTANT EMITTED DURING MALFUNCTION: MEASURES TAKEN TO MINIMIZE EMISSIONS: REASONS WHY FACILITY CANNOT BE SHUTDOWN DURING REPAIRS: CONTINUED OPERATION REQUIRED TO PROVIDE ESSENTIAL* SERVICES:	THIS MALFUNCTION IS OR WILL BE LONGER THAN THE ONE (1) HOUR REPORTING REQUIREMENT? Y
ESTIMATED HOURS OF OPERATION WITH MALFUNCTION CONDITION: DATE/TIME CONTROL EQUIPMENT BACK-IN SERVICE / / 19 AM/PM TYPE OF POLLUTANTS EMITTED: TSP, PM-10, SO2, VOC, OTHER: ESTIMATED AMOUNT OF POLLUTANT EMITTED DURING MALFUNCTION: MEASURES TAKEN TO MINIMIZE EMISSIONS: REASONS WHY FACILITY CANNOT BE SHUTDOWN DURING REPAIRS: CONTINUED OPERATION REQUIRED TO PROVIDE ESSENTIAL* SERVICES:	LOCATION: (CITY AND CO) 1175 North Hoosier Blvd., Peru, Indiana PERMIT NOMSOP103-15670 AFS PLANT ID: 103-00034 AFS POINT ID: INSP: AFS PLANT ID: AFS POINT ID:
DATE/TIME CONTROL EQUIPMENT BACK-IN SERVICE//19AM/PM TYPE OF POLLUTANTS EMITTED: TSP, PM-10, SO2, VOC, OTHER: ESTIMATED AMOUNT OF POLLUTANT EMITTED DURING MALFUNCTION: MEASURES TAKEN TO MINIMIZE EMISSIONS: REASONS WHY FACILITY CANNOT BE SHUTDOWN DURING REPAIRS: CONTINUED OPERATION REQUIRED TO PROVIDE ESSENTIAL* SERVICES:	DATE/TIME MALFUNCTION STARTED:/ 19 AM / PM
TYPE OF POLLUTANTS EMITTED: TSP, PM-10, SO2, VOC, OTHER: ESTIMATED AMOUNT OF POLLUTANT EMITTED DURING MALFUNCTION: MEASURES TAKEN TO MINIMIZE EMISSIONS: REASONS WHY FACILITY CANNOT BE SHUTDOWN DURING REPAIRS: CONTINUED OPERATION REQUIRED TO PROVIDE ESSENTIAL* SERVICES:	ESTIMATED HOURS OF OPERATION WITH MALFUNCTION CONDITION:
MEASURES TAKEN TO MINIMIZE EMISSIONS: REASONS WHY FACILITY CANNOT BE SHUTDOWN DURING REPAIRS: CONTINUED OPERATION REQUIRED TO PROVIDE ESSENTIAL* SERVICES:	DATE/TIME CONTROL EQUIPMENT BACK-IN SERVICE// 19 AM/PM
MEASURES TAKEN TO MINIMIZE EMISSIONS: REASONS WHY FACILITY CANNOT BE SHUTDOWN DURING REPAIRS: CONTINUED OPERATION REQUIRED TO PROVIDE ESSENTIAL* SERVICES:	TYPE OF POLLUTANTS EMITTED: TSP, PM-10, SO2, VOC, OTHER:
REASONS WHY FACILITY CANNOT BE SHUTDOWN DURING REPAIRS: CONTINUED OPERATION REQUIRED TO PROVIDE <u>ESSENTIAL</u> * SERVICES:	ESTIMATED AMOUNT OF POLLUTANT EMITTED DURING MALFUNCTION:
CONTINUED OPERATION REQUIRED TO PROVIDE <u>ESSENTIAL</u> * SERVICES:	MEASURES TAKEN TO MINIMIZE EMISSIONS:
	REASONS WHY FACILITY CANNOT BE SHUTDOWN DURING REPAIRS:
CONTINUED OPERATION NECESSARY TO PREVENT INJURY TO PERSONS:CONTINUED OPERATION NECESSARY TO PREVENT SEVERE DAMAGE TO EQUIPMENT:	CONTINUED OPERATION NECESSARY TO PREVENT INJURY TO PERSONS:

Franklin Power Products, Inc., d/b/a Western Reman Industrial, a division of Franklin Power First Notice-Only Change 103-18655 Page 25 of 25 Peru, Indiana MSOP 103-15670-00034 Permit Reviewer: Aida De Guzman Changed by: Gary Freeman INTERIM CONTROL MEASURES: (IF APPLICABLE)_____ TITLE:____ MALFUNCTION REPORTED BY:_____ (SIGNATURE IF FAXED) MALFUNCTION RECORDED BY:_______DATE:_____TIME:_____ *SEE PAGE 2 PAGE 1 OF 2 Please note - This form should only be used to report malfunctions applicable to Rule 326 IAC 1-6 and to qualify for the exemption under 326 IAC 1-6-4. 326 IAC 1-6-1 Applicability of rule Sec. 1. This rule applies to the owner or operator of any facility required to obtain a permit under 326 IAC 2-5.1 or 326 IAC 2-6.1. 326 IAC 1-2-39 "Malfunction" definition Sec. 39. Any sudden, unavoidable failure of any air pollution control equipment, process, or combustion or process equipment to operate in a normal and usual manner. *Essential services are interpreted to mean those operations, such as, the providing of electricity by power plants. Continued operation solely for the economic benefit of the owner or operator shall not be sufficient reason why a facility cannot be shutdown during a control equipment shutdown. If this item is checked on the front, please explain rationale: